MOL Hungarian Oil and Gas Plc.

Certificate of Quality

ISO 9001:2008 / SGS HU 94/4326

QC_1_MOL1/
mol_qc_english_a

Certificate Number :
451009/3/3933889

Product: Dunawax DWC 0.8-5759/D

MOL_0852_003

Destination: LKL PARAMIX Sp.z.o.o.
Dobra
Bladkowo No. 1-C
PL

Production date: 12.06.2017.
Source: DT00031_M
Batch Number: 1607
SAP Code No: 13000360

Vehicle Number(s): RMI65996 RMI4R99 VYBAR: 0.1%

Property		Method	Specification	Result
Melting Point	°C	ISO 3841	57.0 - 59.0	58.2
Oil Content	%(m/m)	ASTM D 721	max. 0.75	0.22
Viscosity at 100 °C	mm2/s	ISO 3104	3.80 - 4.40	4.217
Penetration at 25 °C	dmm	ASTM D 1321	12 - 17	14
Penetration at 40 °C	dmm	ASTM D 1321	Report	44
Saybolt Color		ASTM D 156	min. 24	30
Sulphur Content	mg/kg	EN ISO 8754	max. 20	7.0
Odour		ASTM D 1833	max. 1	1.0
Ash content	%(m/m)	ISO 6245	max. 0.050	0.001
Paraffin PAH		Ph.Eur.4-4_2.2.25		Passed
Benzene	mg/kg	In-house method	max. 0.50	<0.5
Toluene	mg/kg	In-house method	max. 1.00	<1
Xylene	mg/kg	In-house method	max. 1	<1

MOL Nyrt.
DS Termelés MOL Minőségellenőrzés MOL
2443 Százhalombatta, Olajmunkás u. 2.

Százhalombatta, 2017.06.13. 18:58:56

QC MOL dispatcher